

TransEnergy Inc., Lucey Site, Marshall County, WV



**Photo ID:**  
ACOE Photo 007

**Date:**  
1/18/12

**Description:**  
Lucey  
impoundment



**Photo ID:**  
P1000680

**Date:**  
1/18/12

**Description:**  
WC1 Outlet from  
impoundment





**Photo ID:**

ACOE Photo 002

**Date:**

1/18/12

**Description:**

Dam for  
impoundment



**Photo ID:**

P1000681

**Date:**

1/18/12

**Description:**

Outfall discharges  
into streambed  
stabilized by  
concrete.





**Photo ID:**

P1000688

**Date:**

1/18/12

**Description:**

WC 2 outfall  
(looking towards  
berm)



**Photo ID:**

P1000690

**Date:**

1/18/12

**Description:**

WC2 with fill in  
the foreground





**Photo ID:**

ACOE Photo 011

**Date:**

1/18/12

**Description:**

WC2 looking  
upstream



**Photo ID:**

P1000703

**Date:**

1/18/12

**Description:**

Looking  
downstream  
toward  
impoundment in  
impact area. Note  
bridge and  
backwater  
impacts.





**Photo ID:**

P1000704

**Date:**

1/18/12

**Description:**

Backwater area  
of WC1 looking  
upstream.



**Photo ID:**

P1000693

**Date:**

1/18/12

**Description:**

Impoundment on  
WC3.





**Photo ID:**

P1000701

**Date:**

1/18/12

**Description:**

Outlet from WC3 impoundment. Confluence with WC1 can be seen.



**Photo ID:**

P1000696

**Date:**

1/18/12

**Description:**

Outlet from WC3 impoundment. Confluence with WC1 can be seen.





**Photo ID:**

P1000698

**Date:**

1/18/12

**Description:**

Looking  
upstream of  
WC3  
impoundment.



**Photo ID:**

P1000705

**Date:**

1/18/12

**Description:**

WC4 outlet





**Photo ID:**

P1000708

**Date:**

1/18/12

**Description:**

WC 4